

3M

Scotch-Weld™

Surface Insensitive Instant Adhesives

SI100 • SI1500 • SI Gel

Technical Data

February, 2016

**Product
Description**

3M™ Scotch-Weld™ Surface Insensitive Instant Adhesives bond rough, porous, contaminated, and acidic substrates including wood, cardboard, veneer, fabric, cork, and leather.

Specific Features

- 3M™ Scotch-Weld™ Surface Insensitive Instant Adhesive SI100 is a low viscosity product that will bond a wide variety of materials including plastic, rubber, wood, paper, leather, and metals with a very fast cure speed. It is recommended for use on close-fitting parts and smooth, even surfaces.
- 3M™ Scotch-Weld™ Surface Insensitive Instant Adhesive SI1500 is a surface insensitive cyanoacrylate that has high viscosity and has excellent gap filling capabilities. It relies less on surface moisture for cure speed than standard cyanoacrylates.
- 3M™ Scotch-Weld™ Surface Insensitive Instant Adhesive SI Gel is a fast curing, very high viscosity, gap filling cyanoacrylate. Its gel formation can be used for bonding poorly mating components and for porous substrates such as china and other ceramics and can be used on vertical surfaces as it will not drip or slump.

3M™ Scotch-Weld™

Surface Insensitive Instant Adhesives

SI100 • SI1500 • SI Gel

Typical Uncured Physical Properties

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

	3M™ Scotch-Weld™ Surface Insensitive Instant Adhesives		
	SI 100	SI 1500	SI Gel
Colour	Clear	Clear	Clear
Base	Ethyl Hybrid	Ethyl Hybrid	Ethyl Hybrid
Appearance	Liquid	Liquid	Liquid
Specific Gravity (g/ml)	1.06	1.08	1.10
Viscosity (cps)	71 - 95 ^{1a}	1200 - 1650 ^{1b}	100,000 – 150,000 ^{1c}
Time to Handling Strength (sec)*	3 - 11	15 - 24	6 - 23
Time to full cure (hr)	24	24	24

^{1a} Cone-Plate viscosity, CP75 @ 3000/s shear rate; ^{1b} Cone-Plate viscosity, CP50 @ 100/s shear rate; ^{1c} Brookfield viscosity, Spindle TC @ 2.5 rpm; * On EPDM. Time to handling is substrate dependent.

Typical Cured Physical Properties

Note: The following technical information and data should be considered representative or typical only and should not be used for specification purposes.

	3M™ Scotch-Weld™ Surface Insensitive Instant Adhesives		
	SI 100	SI 1500	SI Gel
Temperature Range (°C)	-54 to 82	-54 to 82	-54 to 82
Gap Fill (in)	0.006	0.008	0.020
	Overlap Shear Strength (psi) ¹		
Steel ²	2109	1694	2510
Stainless Steel ²	2266	2311	3239
Aluminum ²	1689	1766	2652
ABS	914 ³	1005 ³	1337 ³
Polycarbonate	755 ³	667 ³	916 ³
PVC	1096 ³	1053 ³	1764 ³
Nylon	321	283	956
Polypropylene ⁴	728 ³	763 ³	1109 ³
Silicone Elastomer ⁵	105 ³	104 ³	105 ³

¹ ASTM D-1002 ² Grit blasted ³ Substrate failure ⁴ Primed with AC77 ⁵ Primed with AC79

3M™ Scotch-Weld™
Surface Insensitive Instant Adhesives
 SI100 • SI1500 • SI Gel

Hot Strength

Temp(F)	Percent of Initial Strength		
	SI100	SI1500	SI Gel
22	100	100	100
75	75	99	84
100	59	88	41
125	10	48	13

Handling Information

Surface Preparation

For optimum strength structural bonds, paint, oxide films, oils, dust, mold release agents, and all other surface contaminants must be completely removed. However, the amount of surface preparation depends on the required bond strength and the environmental aging resistance desired by the user. Typical quick surface preparation would include wiping with a clean solvent (such as isopropyl alcohol*), abrading the surface with a clean fine abrasive, and then wiping again with a clean solvent to remove loose particles.

Directions for Use

1. Ensure that parts are clean, dry, and free from oil and grease.
2. An instant adhesive activator may be required if there are bonding gaps or porous substrate surfaces, if substrates are low surface energy plastics (e.g., polyethylene, polypropylene) or if substrates have acidic surfaces (e.g., paper, leather).
3. Bond speed is typically very fast so ensure that parts are properly aligned before dispensing.
4. Product is normally hand applied from the bottle. Apply sparingly to one surface and press parts firmly together until handling strength is achieved. As a general rule, as little cyanoacrylate as possible should be used. Over application will result in slower cure speed and lower bond strength.

Cured Bond Characteristics

1. Full bond strength will typically be achieved within a 24 hour cure time.
2. After curing, 3M™ Scotch-Weld™ Surface Insensitive Instant Adhesive bonds are suitable for use up to about 82°C (180°F).
3. Cyanoacrylate bond resistance to most oils and solvents is excellent. Long term humidity, moisture, or water immersion may affect the strength of a cured cyanoacrylate bond depending on the substrates and the bond gap. Testing is recommended to evaluate the effect.

***Note:** When using solvents, extinguish all ignition sources, including pilot lights, and follow the manufacturer's precautions and directions for use.

3M™ Scotch-Weld™ Surface Insensitive Instant Adhesives

SI100 • SI1500 • SI Gel

Storage

For short term storage (<30 days), keep adhesive in a cool (16°C to 27°C [60°F to 80°F]), dry place out of direct sunlight. Keep containers tightly covered and free of moisture. Refrigeration (4°C [40°F]) gives optimum long term storage stability.

Shelf Life

3M™ Scotch-Weld™ Surface Insensitive Instant Adhesives can be expected to have a shelf life of 12 months from the date of shipment from 3M when stored under refrigerated conditions.

Precautionary Information

Refer to Product Label and Material Safety Data Sheet for health and safety information before using this product. For additional health and safety information, call 1-800-364-3577 or (651)737-6501.

Technical Information

The technical information, recommendations and other statements contained in this document are based upon tests or experience that 3M believes are reliable, but the accuracy or completeness of such information is not guaranteed.

Product Use

Many factors beyond 3M's control and uniquely within user's knowledge and control can affect the use and performance of a 3M product in a particular application. Given the variety of factors that can affect the use and performance of a 3M product, user is solely responsible for evaluating the 3M product and determining whether it is fit for a particular purpose and suitable for user's method of application.

Warranty, Limited Remedy, and Disclaimer

Unless an additional warranty is specifically stated on the applicable 3M product packaging or product literature, 3M warrants that each 3M product meets the applicable 3M product specification at the time 3M ships the product. 3M MAKES NO OTHER WARRANTIES OR CONDITIONS, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OR CONDITION OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR ANY IMPLIED WARRANTY OR CONDITION ARISING OUT OF A COURSE OF DEALING, CUSTOM OR USAGE OF TRADE. If the 3M product does not conform to this warranty, then the sole and exclusive remedy is, at 3M's option, replacement of the 3M product or refund of the purchase price.

Limitation of Liability

Except where prohibited by law, 3M will not be liable for any loss or damage arising from the 3M product, whether direct, indirect, special, incidental or consequential, (including lost profits) regardless of the legal theory asserted, including warranty, contract, negligence or strict liability.

ISO 9001: 2000

This Industrial Adhesives and Tapes Division product was manufactured under a 3M quality system registered to ISO 9001:2000 standards.

3M

3M Industrial Adhesives and Tapes Division
3M Canada
London, ON N6A 4T1
1-800-3M-HELPS
www.3M.ca

3M and Scotch-Weld are trademarks of 3M. Used under license in Canada.
© 2016, 3M. All rights reserved. BA-16-21007 160104564 E